



MB 1973 280SE AMG

Vin 108.067-12-018423

April 10-20, 2016 | All works performed at the **Mercedes-Benz of Fort Lauderdale**,
2411 S Federal Highway, FL 33316, USA.

Restoration Report:

- Performed oil change use OEM filter and FUCHS high quality oil TITAN PLUS 15W40
- Flushed coolant system using Mercedes-Benz antifreeze agent
- Replaced power steering fluid MB specs. Fuchs
- Replaced steering coupling between steering box and column
- Replaced power steering high pressure line
- Replaced throttle linkage bushings
- Replaced shifter rod bushings and retaining clips
- Replaced fuel pump and filter (Bosch)
- Cleaned throttle body plate and housing
- Installed harness for additional headlights (Hella original)
- Repaired and resecured wiring in engine compartment
- Replaced spark plugs (Bosch Platinum)
- Installed heat wrap on exhaust manifolds
- Replaced both negative and positive battery post clamps
- Adjusted engine timing and idle, general engine tuning.
- Lubed all suspension joints (Fuchs Renolit black film)

Richard Acevedo

AMG Master Certified Technician

